LEE FLMER F 10/23/81 132531 PRINTER: LI
81 AIT TAIPEI 1200

UNCLASSIFIED

DEPARTMENT OF STATE A/CDC/MR
REVIEWED BY [illegible] DATE 12/15/82
MCE-00 024 W
RPS or XDS EXT. DATE
TS AUTH. REASON(S)
ENDORSE EXISTING MARKINGS
DECLASSIFIED RELEASABLE
RELEASE DENIED
PA or FOI EXEMPTIONS

R 100735Z MAR 81
FM AIT TAIPEI
TO DIR INTL LOG KELLY AFB TX
INFO AIT WASHDC
TAIWAN FMS DAAS GENTILE
HQ AFLC WPAFB OH
CINCPAC HONOLULU HI
UNCLAS SECTION 01 OF 07 TAIPEI 01200
DIR INTL LOG KELLY AFB TX FOR MICW
AIT WASHDC PLS PASS HQ USAF FOR PAIE AND PASS CCNAA
TAIWAN FMS DAAS DAYTON OH FOR AF LCC TAINAN
HQ AFLC WPAFB OH FOR MI TW
CINCPAC HONOLULU HI FOR J465
E.O. 12065: N/A
TAGS: MASS, TW, US
SUBJECT: TAF AGENDA ITEMS
REF: KELLY/MICW 062030Z MAR 81 (NOTAL)
1. REF REQUESTED COPY OF TAF AGENDA ITEMS. AIT/T RECEIVED COMPLETED COPY 9 MAR.
2. TAF AGENDA ITEMS:
A. ITEM 1
-- SUBJECT: LGE FLIGHT LINE COMPUTER TEST SET AN/GTM-51.
-- DESCRIPTION: FOUR (4) SETS TTU-394/E LGB TEST

EQUIPMENT PURCHASED FOR PURPOSE OF FIELD MAINTENANCE CANNOT EFFECTIVELY CARRY OUT FLIGHT LINE LGB LOADING TEST.
-- RECOMMENDATION: REQUEST SUBJECT EQUIPMENT (9 SETS) BE INCLUDED IN YAL TOOL ITEM UNDER FMS CASE TW-D-YAG.
B. ITEM 2
-- SUBJECT: DATA AND AVAILABILITY OF 30MM CANNON KIT FOR F-5E/F
-- DESCRIPTION: PURPOSE FOR ADDING 30MM CANNON ON F-5E/F AIRCRAFT IS TO STRENGTHEN FIRING POWER.
-- RECOMMENDATION: REQUEST USAF PROVIDE TAF WITH PERFORMANCE AND AVAILABILITY DATA FOR 30MM CANNON AS WELL AS DETAILED DESCRIPTION FOR INSTALLING CANNON ON F-5 AIRCRAFT.
C. ITEM 3
-- SUBJECT: DELIVERY OF AGM-65 MAVERICK MISSILES AT EARLIER DATE.
-- DESCRIPTION:
-- (1) ORIGINAL SCHEDULE FOR EIGHTEEN (18) TRAINING

MISSILES TO BE DELIVERED MARCH - MAY 1982.
-- (2) ORIGINAL SCHEDULE FOR FIVE HUNDRED (500) OPERATIONAL MISSILES TO BE DELIVERED OCTOBER - DECEMBER 1982.
UNCLASSIFIED
UNCLASSIFIED
PAGE 03 AIT TA 01200 01 OF 07 100820Z
-- RECOMMENDATION:
-- (1) REQUEST USAF DELIVER TRAINING MISSILES ACCORDING TO ORIGINAL SCHEDULE FOR TRAINING.
-- (2) REQUEST USAF DELIVER 100 EACH OPERATIONAL MISSILES AT AN EARLIER DATE THAN MARCH 1982.
D. ITEM 4
-- SUBJECT: EXCESSIVE REJECT RATES FOR TACAN AND SIF
-- DESCRIPTION:
-- (1) TWENTY-THREE (23) SETS TACAN (AIR NO. 81-8273)R/T-ARN-118 AND SIF (AIR NO. 8275) R/T-APX-101 USED FOR VE1001-VE1014 AND VF1001-VE1019 AIRCRAFT RECEIVED. FIVE (5) SETS EACH FOUND NOT FUNCTIONING WELL. MALFUNCTIONING TACANS.

S/N	DISCREPANCY	TESTED PER NAG'S ITWO
20563	NO ID TONE IN THE HEADSET	993119 PARA 1,7,1,5
20544	NO ID TONE IN THE HEADSET	993119 PARA 1,7,1,5
20575	NO POWER OUTPUT ON THE SIMULATOR	993119 PARA 1,7,4
20644	AFTER TACAN LOCKED ON THE	993119 PARA 1,7,15,3

NOTE BY CC/T: NOT PASSED TO CCNAA.
UNCLASSIFIED
UNCLASSIFIED
PAGE 04 AIT TA 01200 01 OF 07 100820Z
UNCLASSIFIED

LEE ELMER E 10/26/81 102532 PRINTER: LL
81 AIT TAIPEI 1200
UNCLASSIFIED
UNCLASSIFIED
PAGE 01 AIT TA 01200 02 OF 07 100826Z
ACTION AIT-02
INFO OCT-01 ADS-00 EA-12 DODE-00 PM-09 MCE-00 /024 W
101640 101330Z /44
R 100735Z MAR 81
FM AIT TAIPEI
TO DIR INTL LOG KELLY AFB TX
INFO AIT WASHDC
TAIWAN FMS DAAS GENTILE
HQ AFLC WPAFB OH
CINCPAC HONOLULU HI
UNCLAS SECTION 02 OF 07 TAIPEI 01200
— 389 MILE TARGET, PRESS AND
— RELEASE THE SELF TEST BUTTON,
— THE READING OF THE HSI RANGE
— MIDICATOR DID NOT MEET THE
— LIMIT 220.2 2.5 NM.
20639 WHEN BEACON SIMULATOR 993119 PARA 1,7,12,7 -
— ATTENUATION CONTROL SET 1,7,12,8
— TO -85 DBM, AND SIMULATOR
— BEARING TO "000.0" DEGREES
— UNABLE TO ADJUST HSI COURSE
— SELECT KNOB TO THE COURSE
— DEVIATION INDICATOR BAR
— CENTERS.
MALFUNCTIONING SIFS
S/N DISCREPANCY TESTED PER NAG'S ITWO
WP0635 SETTING TO MODE 1 AND 993129 PARA 5,15,1
— CODES 10, 30, 70 BOTH
— ON CONTROL UNIT AND
— ON TEST SET APM-123,
UNCLASSIFIED
UNCLASSIFIED
PAGE 02 AIT TA 01200 02 OF 07 100826Z
— ACCEPT LIGHT ON APM-
— 123 NOT ILLUMINATED.
AP0547 PILOT SQKS THE SIF FAILED
— IN SECOND FLIGHT.
S/N DISCREPANCY TESTED PER NAG'S ITWO
WP0492 ACCEPT INDICATOR LIGHT 993129, PARA 9,7
— DID NOT ILLUMINATE AND
— REJECT INDICATOR LIGHT
— FAILED TO GO OUT.
— CANNOT GET STANDARD
— DECIBEL NUMBER.
WP0740 ACCEPT INDICATOR DOES 993129 PARA 7, 10
— NOT DISPLAY A STEADY
— LIGHT. CANNOT GET
— STANDARD DECIBEL NUMBER.
WP0739 ACCEPT INDICATOR DOES 993129 PARA 7, 10
UNCLASSIFIED / PAGE 3

DECLASSIFIED

— NOT DISPLAY A STEADY
— LIGHT. THE DECIBEL
— NUMBER CANNOT BE STAND-
— ARDIZED.
— (2) ACCORDING TO PAGE 2, ANNEX 2 TO MR. CARDOZA'S MEMORANDUM OF JUNE 25 1980, TACAN AND SIF ITEMS INSPECTED 100 PER CENT BY NORTHROP.
— (3) BECAUSE OF EXCESSIVE REJECTION RATES OF THESE TWO ITEMS, QUALITY MUST BE UPGRADED. OTHERWISE, AILC WILL PROBABLY BE FORCED TO SUSPEND WORK.
UNCLASSIFIED
UNCLASSIFIED
PAGE 03 AIT TA 01200 02 OF 07 100826Z
— RECOMMENDATION:
— (1) REQUEST USAF REQUIRE MANUFACTURES TO UPGRADE QUALITY AND INTENSIFY QUALITY CONTROL.
— (2) REQUEST NORTHROP INTENSIFY INSPECTIONS PRIOR TO SHIPMENT.
E. ITEM 5
— SUBJECT: CANNONS AND CAD/PAD'S FOR PEACE TIGER V.
— DESCRIPTION: TEN (10) LEFT GUNS REQUIRED FOR PEACE TIGER IV (F-5FC X 9 AND F-5EC X 11) RECEIVED THREE (3) MONTHS LATER THAN PRESET SCHEDULE (ARRIVED 17 FEB.) SERIOUSLY AFFECTING PROGRESS OF AIRCRAFT PRODUCTION.
— RECOMMENDATION: REQUEST USAF SUPPLY CANNONS AND CAD/PAD'S FOR PEACE TIGER V IN ACCORDANCE WITH SCHEDULE.
F. ITEM 6
— SUBJECT: THREE (3) UNDELIVERED MATERIAL ITEMS
— FOR MODIFICATION OF "C" CONFIGURATION
— IN PEACE TIGER 111.
— DESCRIPTION:
— (1)ACODING TO USAF MESSAGE R191735Z MAY 1978, FIFTEEN (15) MATERIAL ITEMS REQUIRED TO BE DELIVERED
UNCLASSIFIED

DECLASSIFIED

LEE ELMER E 10/23/81 132562 PRINTER LI
81 AIT TAIPEI 1200 DECLASSIFIED
UNCLASSIFIED
UNCLASSIFIED
PAGE 01 AIT TA 01200 03 OF 07 100832Z
ACTION AIT-02
INFO OCT-01 ADS-00 EA-12 DODE-00 PM-09 MCE-00 024 W
101654 101331Z /44

R 100735Z MAR 81
FM AIT TAIPEI
TO DIR INTL LOG KELLY AFB TX
INFO AIT WASHDC
TAIWAN FMS DAAS GENTILE
HQ AFLC WPAFB OH
CINCPAC HONOLULU HI
UNCLAS SECTION 03 OF 07 TAIPEI 01200
TO AIDC BECAUSE OF CONFIGURATION MODIFICATION TO
FOURTEEN (14) AIRCRAFT.
-- (2)RECEIVING STATUS AS FOLLOWS:

-- ITEM	QTY SHOULD BE DELIVERED	QTY RECEIVED BY AIDC	REMARKS
-- 2	14	18	4
-- 7	14	12	-2
-- 9	14	12	-2
-- 10	14	12	-2

-- (3) THE 4 EA (ITEM NO. 2) OVER-RECEIVED BY AIDC
WILL BE SHIPPED TO NORTHROP IMMEDIATELY.
-- RECOMMENDATION: REQUEST USAF SHIP UNDELIVERED
ITEMS OF MATERIALS NO. 7, 9, 10 TO AIDC ASAP.
G. ITEM 7
UNCLASSIFIED
UNCLASSIFIED
PAGE 02 AIT TA 01200 03 OF 07 100832Z
-- SUBJECT: REESTABLISHMENT OF PROCEDURES FOR RETURN
-- AND REPLACEMENT OF REJECTED GFAE ITEMS.
-- DESCRIPTION:
-- (1) AT EARLY STAGE, REJECTED ITEMS OF GFAE
UNQUALIFIED EQUIPMENT RECEIVED IN PEACE TIGER PROGRAM
RETURNED TO NORTHROP FOR REPLACEMENT OR REPAIR IN
ACCORDANCE WITH RDR PROCEDURE. SUPPORT CONDITION WAS
GOOD.
-- (2) SINCE USAF SUGGESTED CHANGE PROCEDURE TO
ROID'S IN PEACE TIGER III REVIEW CONFERENCE, AIDC
HAS COMPLETED ROID FORMS AND TOGETHER WITH REJECT
ITEMS SENT TO TAF/AFLC FOR FORWARDING TO USAF.
BECAUSE USAF HAS NOT TAKEN ACTION ON THIS MATTER,
REJECTED ITEMS RETURNED HAVE BEEN ACCUMULATED AND
ONE YEAR GUARANTIES ARE OVERDUE.
-- (3) IN PEACE TIGER V REVIEW CONFERENCE, USAF
SUGGESTED AGAIN THAT AIDC'S REJECTED GFAE ITEMS SHOULD
BE SHIPPED TO US THROUGH AFLC REPARABLE RETURN PRO-
CEDURE (SEE PARAGRAPH 1-N OF MINUTES PEACE TIGER V
REVIEW CONFERENCE HELD IN NOV, 1979). HOWEVER TO
IMPLEMENT SAID PROCEDURE, AIDC WILL ENCOUNTER SOME
UNCLASSIFIED / PAGE 5

LEE ELMER E 10/23/81 132533 PRINTER: LI
81 AIT TAIPEI 1200

UNCLASSIFIED

PROBLEMS. CURRENT REJECTED ITEMS WHICH HAVE ALREADY BEEN INSPECTED AND SPOT-CHECKED OR 100 PER CENT INSPECTED BY NORTHROP, STILL FOUND IN BAD CONDITION THROUGH BENCH TEST OR AIRCRAFT ACTUAL OPERATION ARE AS FOLLOWS:

AIDC GFAE REJECTION STATUS (NEW PROCEDURE)

UNCLASSIFIED

UNCLASSIFIED

PAGE 03 AIT TA 01200 03 OF 07 100832Z

AERO NO.	NOMENCLATURE	QTY	ROID/RDR NO.
41-1423	MAIN WHEEL	1	Q002
41-1424	BRAKE	2	Q111,QF-80-3147
42-0653	G.C.U.	11	Q024, Q031, Q032, Q037
--			Q041, Q045, Q062, Q122
--			Q130. Q152, Q155
46-0115	LOX COVERTER	6	Q012, Q015, Q058, Q092
--			Q095, Q103
46-2117	LOX COVERTER	4	Q116, Q117, Q148,
--			QF-80-3162
46-1010	LOX QTY IND	6	Q005, Q006, Q016, Q023
--			QF-80-3159(2)
AERO NO.	NOMENCLATURE	QTY	ROID/RDR NO.
46-4000	LOX VALVE	1	Q175
60-1209	CLOCK	2	Q034, Q101
60-1500	SERVO AMPLIFIER	2	Q019, Q026
60-1657	DETECTOR	1	QF-81-042
60-3177	NOZZLE POST IND	1	Q073

UNCLASSIFIED

UNCLASSIFIED

CC\<<<\

LEE ELMER E 10/23/81 132563 PRINTER LI
81 AIT TAIPEI 1200

UNCLASSIFIED

UNCLASSIFIED
PAGE 01 AIT TA 01200 04 OF 07 100839Z
ACTION AIT-02
INFO OCT-01 ADS-00 EA-12 DODE-00 PM-09 MCE-00 024 W
101751 101331Z /44

R 100735Z MAR 81
FM AIT TAIPEI
TO DIR INTL LOG KELLY AFB TX
INFO AIT WASHDC
TAIWAN FMS DAAS GENTILE
HQ AFLC WPAFB OH
CINCPAC HONOLULU HI
UNCLAS SECTION 04 OF 07 TAIPEI 01200

60-5938	RATE SW GYRO	2	Q055, QF-81-041
60-6357	VERT VEL IND	2	Q020, Q191
60-6403	ALTIMETER	4	Q042, Q270, Q277, Q087
--			DELETE FOR EC AND FC
60-6422	ALTITUDE IND	3	Q083, QF-79-3280,
--			QF-80-3161
60-6429	AIRSPEED IND	13	Q014, Q080, Q100, Q113
--			Q119, Q125, Q131, Q133
--			Q140, Q167, Q185, Q186
--			QF-81-040
60-6433	ACCELEROMETER	2	QE-80-224, 225
60-6434	DISPLACEMENT GYRO	5	Q052, Q060, Q078,
--			Q121, Q142
60-6435	ATTITUDE IND	1	Q003
60-6441	C.A.D.C.	14	Q008, Q013, Q029, Q030,

UNCLASSIFIED
UNCLASSIFIED
PAGE 02 AIT TA 01200 04 OF 07 100839Z

--			Q046, Q065, Q076, Q084,
--			Q085, Q096, Q102, Q172,
--			Q174, Q189
60-6442	PITCH TRIM IND	4	Q035, Q135, Q164,
--			QF-81-012
60-6446	ATTITUDE IND	1	Q144
60-6458	AOA TRANSMITTER	1	Q150
AERO NO.	NOMENCLATURE	QTY	ROID/RDR NO.
60-6460	ALTIMETER	1	QF-80-3158
60-6461	H.S.I.	5	Q050, Q114, Q157,
--			Q165, Q176
61-2358	HYD PRESS TRANS	2	Q059, Q158
61-2501	HYD PRESS IND	8	Q028, Q089, Q097,
--			Q151, Q173, Q183,
--			QF-81-004, QF-81-019
61-3131	OIL PRESS TRANS	11	Q017, Q124, Q154, Q170,
--			Q178(3), Q187(2),
--			Q188, QF-81-002
61-3140	TACHOMETER	7	Q051, Q092, Q156, Q163,
--			Q165, Q169, Q192

61-3155	EGT IND	2	Q145, Q168

UNCLASSIFIED
UNCLASSIFIED

61-3156	FUEL FLOW IND	6	Q067, Q104, Q115, Q123,
--			DELETE FOR EC & FC
--			Q138, Q153
61-3157	FUEL FLOW TRANS	5	Q088, Q094, Q120
--			WF-80-3123, QF-80-3142
61-3162	OIL PRE IND	3	Q001, Q081, Q137
74-0693	CAMERA -	4	Q051, Q136, Q143, Q159
81-0209	AMPLIFIER	5	Q027, Q105, Q109,
--			QF-80-3134, QF-80-3154
81-0720	ANTENNA	2	Q018, Q132
81-2441	CONTROL	2	Q063, Q086
81-2447	CONTROL	2	Q190, Q194
81-2509	CONVERTER	5	Q021, Q025, Q056,
--			Q068, Q182
AERO NO.	NOMENCLATURE	QTY	ROID/RLR NO.
81-8138	RADIO SET	8	Q007, Q048, Q049, Q053
--			Q110, Q112, Q118, Q139
81-8269	RT ARN-84	12	Q040, Q047, Q054, Q057
--			Q066, Q074, Q075, Q082
--			Q093, Q098, Q099, Q107
81-8273	R/T ARN-118	5	Q180, Q181, Q184, Q193
--			QF-80-3163
83-8275	R/T APX-101	5	Q177, Q179, QF-80-3115,
--			3116, QF-80-3132

UNCLASSIFIED
UNCLASSIFIED

UNCLASSIFIED

LEE ELMER E 10/23/81 132535 PRINTER: LI
81 AIT TAIPEI 1200 UNCLASSIFIED

UNCLASSIFIED
PAGE 01 AIT TA 01200 05 OF 07 100845Z
ACTION AIT-02
INFO OCT-01 ADS-00 EA-12 DODE-00 PM-09 MCE-00 /024 W
102025 101333Z /44

R 100735Z MAR 81
FM AIT TAIPEI
TO DIR INTL LOG KELLY AFB TX
INFO AIT WASHDC
TAIWAN FMS DAAS CENTILE
HQ AFLC WPAFB OH
CINCPAC HONOLULU HI
UNCLAS SECTION 05 OF 07 TAIPEI 01200

81-4360	MOUNT	1	QF-81-018
86-0101	ALTIMETER	2	Q128, Q141
86-0150	CONTROL	4	Q036, Q038, Q039, Q161
86-0406	REC/XMTR	7	Q009, Q010, Q011, Q013
--			Q033, Q043, Q134
86-0425	SWITCHING UNIT	1	Q106
86-0452	TEST SET	2	Q079, Q147
--	TOTAL	206	

BESIDES, USAF SUGGESTION FOR SHIPPING REJECTED ITEMS AS REPARABLES TO U.S. FOR REPAIR RESULTS IN TWO OTHER PROBLEMS:
-- (A) IN BEGINNING, TAF PURCHASED NEW OR SERVICEABLE ITEMS FROM USAF. WHEN DEFECTS FOUND BY AILC IN RECEIVING AND INSPECTING ITEMS, IT IS REASONABLE THAT USAF SHOULD BE FULLY RESPONSIBLE FOR REPLACEMENT. NOW USAF NOT

UNCLASSIFIED
UNCLASSIFIED
PAGE 02 AIT TA 01200 05 OF 07 100845Z

ONLY REFUSES TO REPLACE SAID ITEMS, BUT ALSO WANTS TAF TO PAY REPAIR COST (ABOUT 50 PER CENT OF THE ORIGINAL PRICE) AND 17 PER CENT FRIEGHT. OBVIOUSLY, THIS IS UNREASONABLE.
-- (B) OCCURRENCE OF REJECTED ITEMS WOULD IMPACT PROGRESS OF F-5E/F PRODUCTION WHEN TAF HAS NO SPARES OR STOCK ON HANL.
(4). ONE YEAR GUARANTY FOR GFAE ITEMS CALCULATED FROM LATE WHEN USAF DELIVERS ITEMS TO NORTHROP FOR RECEIPT. ITEMS INSPECTED BY NORTHROP WILL NOT BE SHIPPED TO AIDC UNTIL THEY ARE REQUIRED. WHEN ITEMS FOUND DEFECTIVE DURING ACCEPTANCE INSPECTION BY AIDC AND THEN SHIPPED TO TAF/AFLC FOR FORWARDING TO U.S. THE ONE YEAR GUARANTY PERIOD WILL BE OVER DUE. IN SUCH CASE, TAF HAS TO PAY REPAIR COSTS AND FREIGHT.
-- RECOMMENDATION:
(1) REQUEST REJECTED ITEMS BE RETURNED TO NORTHROP FOR REPLACEMENT OR REPAIR FREE OF CHARGE IN ACCORDANCE WITH THE EARLIEST RDR PROCEDURE.
(2) IF RDR PROCEDURE CANNOT BE ADOPTED THEN:

(A) REQUEST USAF ASK NORTHROP TO MAKE 100 PER CENT INSPECTION ON GFAE TO BE SHIPPED TO AIDC.

(B) REQUEST NORTHROP PERSONNEL IN TAIWAN BE AUTHORIZED BY USAF TO MAKE ACCEPTANCE INSPECTION IN CONJUNCTION WITH AIDC. SHOULD ITEMS BE PROVEN TO BE IN BAD CONDITION, THEY WOULD BE RETURNED TO US FOR REPAIR FREE OF CHARGE

OR FOR REPLACEMENT WITHOUT ANY CONDITION.

(C) FOR REJECTED ITEMS WHICH WERE 100 PER CENT INSPECTED BY NORTHROP AND ARE THEN FOUND DEFECTIVE IN ACCEPTANCE INSPECTION BY AIDC, REQUEST USAF CONCUR IN REPAIRING OR REPLACING FREE OF CHARGE.

— (D) REQUEST NORTHROP DELIVER GFAE ITEMS TO FORWARDER NLT 30 DAYS AFTER THEIR RECEIPT SO AS TO OBTAIN THE TIME ELEMENT OF THE GUARANTY.

H. ITEM 8

— SUBJECT: M37-T20 TEST STANDS DISCREPANCY

— (4920-01-041-5863, DTW 544-9309-6072)

— UNDER FMS CASE TW-D-SES FOR PEACE TIGER V

— DESCRIPTION: AFTER TAF SUBMITTED REPORT OF ITEM DISCREPANCY (ROID) ON THE TRANSPORTATION DISCREPANCY OF M37 TEST STANDS, USAF CONCURRED IN SHIPPING DISCREPANT ITEMS FIRST TO PHILIPPINES OR JAPAN, AND THEN TO KELLY AFB BY SAID TWO COUNTRIES. HOWEVER, DUE TO FACT THAT THERE ARE NO DIPLOMATIC TIES WITH THOSE TWO COUNTRIES NOR LIAISON OFFICES, TAF UNABLE TO TAKE ANY ACTION ON THIS MATTER.

— RECOMMENDATION: REQUEST THAT TAF BE PROVIDED WITH A CONUS ADDRESS FOR SHIPPING DISCREPANT ITEMS.

I. ITEM 9

— SUBJECT: EQUIPMENT REQUIRED FOR CONVERSION OF THE

LEE ELMER E 10/26/81 102536 PRINTER: LI
81 AIT TAIPEI 1200

UNCLASSIFIED

UNCLASSIFIED
PAGE 01 AIT TA 01200 06 OF 07 100853Z
ACTION AIT-02
INFO OCT-01 ADS-00 EA-12 DODE-00 PM-09 MCE-00 /024 W
102106 1013412 /44

R 100735Z MAR 81
FM AIT TAIPEI
TO DIR INTL LOG KELLY AFB TX
INFO AIT WASHDC
TAIWAN FMS DAAS GENTILE
HQ AFLC WPAFB OH
CINCPAC HONOLULU HI
UNCLAS SECTION 06 OF 07 TAIPEI 01200
-- DESCRIPTION:
-- (1) FORTY THREE (43) ITEMS OF EQUIPMENT LISTED BELOW REQUIRED UNDER FMS CASE TW-L-SES. DUE TO POOR AND UNSTABLE SUPPLY STATUS, SUPPLY OF EQUIPMENT CANNOT MEET REQUIREMENT OF CONVERSION SCHEDULE.

NSN	P/N	DOC NO	SUPPLY STATUS	
1450007666856	58A46264U	DTW54493095803	BP 1359	
1730000513537	POG0326	DTW54493095810	BP 1365	
1730010132638	18-76005-1	DTW54493095847	BP 1365	X
1730010388363	14-76059-501	DTW54493095849	BP 1365	X
3655005340564	5506496	DTW54493095868	BP 1365	
4920001499456	14-76011-1	DTW54493095928	BP 2090	
4920001716719	13A6900	DTW54493095938	BP 1304	X
4920001757867	14-76029-1	DTW54493095941	BP 1365	
4920001757868	14-76035-1	DTW54493095942	BP 1365	
4920002287717	14-76025-501	DTW54493095952	BP 1365	
4920002795120	633555-1	DTW54493095953	BP 1365	X
4920004115503	2103827G01	DTW54493095977	BP 1365	

UNCLASSIFIED
UNCLASSIFIED
PAGE 02 AIT TA 01200 06 OF 07 100853Z

4920004203457	1635-2A	DTW54493095980	BP 1365	
4920004334510	2103215G01	DTW54493095981	BP 1365	
4920004580686	14-76023-1	DTW54493095987	BP 1365	
4920004741005	13A0850	DTW54493095990	BP 1365	X
4920004899110	TTU205C/E	DTW54493095992	BP 1260	X
4920004849076	14-76005-501	DTW54493095991	BP 1304	X
4920005639200	185F492G2	DTW54493096074	BP 1365	X
4920008392488	230E65G2	DTW54493096041	BP 1365	X
4920008710116	13A1492	DTW54493096042	BP 1365	X
4920010081532	2103887G02	DTW54493096065	BP 1330	X

NSN	P/N	DOC NO	SUPPLY STATUS
4920010174497	18-76007-1	DTW54493096069	BP 1365
4940000646705	SE01420	DTW54493096098	BV 1360
5120000012660	21C6086G01	DTW54493096110	BP 1365
5120000032220	14-76038-1	DTW54493096111	BP 1365

LEE ELMER E 10/23/81 132536 PRINTER 11
81 AIT TAIPEI 1200
UNCLASSIFIED
4920001507197 633176-307 DTW54493095932 BP 1234
5120002093984 14-76061-1 DTW54493096141 BP 1365
5120004031632 21C6047G01 DTW54493096159 BP 12) 3:3 7 61200040
83994 21C6021G01 DTW54493096164 BP 1365 X
(5130007094101) 21C532 DTW54493096253 BP 1365
5130010595049
5180003294167 11309048G1 DTW54493096256 BP 1365
5180004438769 14076137-1 DTW54493096259 BP 1350
5220000906764 21C6084G01 DTW54493096271 BP 1365 X
6610004279220 AGU-13A DTW54493096355 BP 1212 X
6625000041656 14-76024-1 DTW54493096365 BP 1365
6625000051183 6-76505-501 DTW54493096366 BV 2120
6625001646551 APM2454 DTW54493096385 B1 1365
6625004660586 3310A DTW54493096414 BP 1365
6625005836578 AFB2PC332CCNBR DTW54493096425 BP 1365
UNCLASSIFIED
UNCLASSIFIED
PAGE 03 AIT TA 01200 06 OF 07 -102853Z
6625005918360 86408CPT3 DTW54493096427 BP 1365
6625007247979 MILG9987 DTW54493096432 BP 1365
6920007022934 2900768-1 DTW54493105803 BP 1212 X
X : MOST CRITICAL ITEMS
(2) SIXTEEN (16) ITEMS MARKED WITH AN X ABOVE CRITICALLY NEEDED. REQUEST THAT THEY BE DELIVERED AND SHIPPED UNDER HIGH PRIORITY.
-- RECOMMENDATION: REQUEST SUPPLY STATUS BE IMPROVED AND DATE FOR DELIVERY OF 16 CRITICALLY NEEDED ITEMS BE ADVANCED TO JUNE 1981 AND REMAINING ITEMS SHIPPED AUGUST 1981.
J. ITEM 10
-- SUBJECT: CRITICAL ITEMS PECULIAR TO F-5E/F C
-- CONFIGURATION AIRCRAFT
-- DESCRIPTION: SIX (6) ITEMS FOR F-5E/F C CONFIGURATION AIRCRAFT OFTEN IN NMCS CONDITION. POOR SUPPLY STATUS CAUSES SUPPORT DIFFICULTY.

NSN	NOUN	QTY	DOC NO
6615YET614634	DIRECTOR GYROSCOPE	2 EA	DTW44V03130091
--		1 EA	DTW44V10160091
--		2 EA	DTW44V10310492
1270010717473	RADAR	1 EA	DTW44V02393018
--		5 EA	DTW44V02661501
--		2 EA	DTW44V03660003
--		4 EA	DTW54493235869

UNCLASSIFIED

LEE ELMER E 10/23/81 132557 PRINTED LI
81 AIT TAIPEI 1200 UNCLASSIFIED

UNCLASSIFIED
PAGE 01 AIT TA 01200 07 OF 07 100858Z
ACTION AIT-02
INFO OCT-01 ADS-00 EA-12 DOLE-00 PM-09 MCE-00 024 W
102120 1013422 /44
R 100735Z MAR 81
FM AIT TAIPEI
TO DIR INTL LOG KELLY AFB TX
INFO AIT WASHDC
TAIWAN FMS DAAS GENTILE
HQ AFLC WPAFB OH
CINCPAC HONOLULU HI
UNCLAS SECTION 07 OF 07 TAIPEI 01200

1270010774724	RCVR/XMTR	1 EA	DTW44V02321591
--		2 EA	DTW44V02393020
--		4 EA	DTW44V02661502
--		1 EA	DTW44V02760001
--		1 EA	DTW44V10430625
--		8 EA	DTW54493235880
589500539 1911	SIF	1 EA	DTW44V02630001
--		1 EA	DTW44V02740002
--		1 EA	DTW44V03220002
--		2 EA	DTW44V03590606
--		1 EA	DTW44V10230607
--		1 EA	DTW54493096296
--		5 EA	DTW54493236201
1680010697741	CONTROL GUN	1 EA	DTW54V03060201
--		2 EA	DTW54493236283
1270010637873	APQ-159 ANTENNA	1 EA	DTW44V03510001
--		1 EA	DTW44V03660002
--		1 EA	DTW44V10430602
--		5 EA	DTW54493235862

UNCLASSIFIED
UNCLASSIFIED
PAGE 02 AIT TA 01200 07 OF 07 100858Z
RECOMMENDATION: REQUEST ABOVE CRITICAL ITEMS BE
DELIVERED PROMPTLY TO AS TO FACILITATE SUPPORT OF
UNIT TRAINING. CROSS
UNCLASSIFIED

UNCLASSIFIED